



# VEHICLE INSPECTION REPORT

**LJ63KUB**

## Citroen C4 1.6 VTi Selection 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama  
GRADE  
**5**

### Details

Reg. date	02/09/2013	Body Style	Hatchback	Last service miles	42,600
Year	2013	Keys	2	MOT Due	27/10/2026
Mileage	49,247 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	5
Colour	BLACK	Number of stamps	11	Doors	5
VIN	VF7NC5FS0DY579913	Last service date	02/10/2024		

£90 ADDITIONAL FEE

last service 2/10/24 @ 42,600 miles ( 11 services 4 main dealer) Service light on

### Tyres

NSF	BUDGET	6.0mm
NSR	MICHELIN	4.0mm
OSF	MICHELIN	3.0mm
OSR	MICHELIN	5.0mm
Spare		

## Features


- Bluetooth connection
- Radio/CD
- Air conditioning
- Rear headrests
- Passenger airbag
- Cloth seat trim
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Alloy wheels
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Central locking
- Telephone
- Fixed panoramic glass roof
- Rear electric windows
- Drivers airbag
- Remote central locking

## Photos





## Condition Check



## Damage Photos



1: Wheel of  
Scratched  
Over 50mm



2: Wing of  
Chipped  
1 To 5



3: Door osf  
Scratched  
Over 25mm Thru Paint



4: Door osr  
Scratched  
Over 25mm Thru Paint



5: Wheel osr  
Corroded  
Light



6: Bumper Rear  
Scratched  
Over 100mm Thru Paint



7: Qtr Panel osr  
Dented  
Over 2 UpTo 10mm



8: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint



9: Wheel nsr  
Scratched  
Over 50mm



10: Door nsr  
Dented  
Over 30% Of Panel



11: Sill ns  
Dented  
With Paint Damage



12: Door nsf  
Dented  
Over 30% Of Panel



13: Wing nsf  
Chipped  
1 To 5



14: Wheel nsf  
Scratched  
Over 50mm



15: Wing nsf  
 Scratched  
 Over 25mm Not Thru Paint



16: Bumper Front  
 Scratched  
 Over 100mm Thru Paint



17: Bonnet  
 Chipped  
 Multiple Chips

**Interior**

**Carpet Condition**                      Average  
**Seat Condition**                        Average

**Upholstery Condition**              Average  
**Odour**                                      No

**Vehicle Inspection Report**

**Disclaimer**

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	Fault
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK