



# VEHICLE INSPECTION REPORT

**YE20OUY**

## Skoda Karoq 1.0 TSI SE 5dr

nama  
GRADE  
**3**

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

### Details

Reg. date	29/07/2020	Body Style	Estate	Last service miles	90,710
Year	2020	Keys	2	MOT Due	19/10/2026
Mileage	105,301 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Printout	Gears	6
Colour	WHITE	Number of stamps	3		
VIN	TMBKP7NU1L5040331	Last service date	17/10/2025		

£90 ADDITIONAL FEE

Last service 17/10/2025 at 90,710 miles- 3 main dealer services. Print

### Tyres


NSF	ACCELERA	2.0mm
NSR	AUTOGREEN	5.0mm
OSF	ACCELERA	2.0mm
OSR	AUTOGREEN	5.0mm
Spare		

## Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Cruise control
- Steering wheel mounted controls
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- PAS
- Digital radio
- Roof rails
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5



2: Bumper Front  
Chipped  
1 To 5



3: Wheel nsf  
Scratched  
Up To 50mm



4: Door nsf  
Dented  
Over 30mm



5: Door osr  
Chipped  
1 To 5



6: Bumper Rear  
Chipped  
1 To 5



7: Door osr  
Dented  
Between 10mm + 30mm



8: Door osf  
Chipped  
Edge Chip



9: Wing osf  
Dented  
With Paint Damage

10: Roof  
Chipped  
Edge Chip

**Interior**

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

**Vehicle Inspection Report**

**Disclaimer**

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK