



# VEHICLE INSPECTION REPORT

**YL16GGZ**

## Citroen Grand C4 Picasso 1.6 BlueHDi Selection 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama  
GRADE  
**4**

### Details

Reg. date	04/07/2016	Body Style	MPV	Last service miles	43,638
Year	2016	Keys	2	MOT Due	29/06/2026
Mileage	46,210 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Service Book	Gears	6
Colour	RED	Number of stamps	8		
VIN	VF73ABHZMGJ680992	Last service date	20/06/2025		

Drive belt replaced 26/06/2024 at 40465 miles.  
 Last service 20/06/2025 at 43638 miles (8 services). Book & print.

### Tyres


NSF	DUNLOP	5.0mm
NSR	GOODYEAR	5.0mm
OSF	DUNLOP	5.0mm
OSR	EXCELON	5.0mm
Spare		

## Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Central locking
- Cruise control
- Steering wheel mounted controls
- Fixed panoramic glass roof
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- PAS
- Digital radio
- Front fog lights
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Cloth seat trim
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels

## Photos





## Condition Check



## Damage Photos



1: Other  
N/A  
N/A



2: Bonnet  
Chipped  
1 To 5



3: Bumper Front  
Scratched  
25 to 100mm Thru Paint



4: Roof  
Dented  
Over 30mm



5: Wheel nsf  
Scratched  
Over 50mm



6: Door Mirror Assy nsf  
Scratched (Painted)  
UpTo 25mm Thru Paint



7: Door nsf  
Chipped  
Edge Chip



8: Door nsr  
Scratched  
UpTo 25mm Thru Paint



9: Wheel nsr  
Scratched  
Over 50mm



10: Qtr Panel nsr  
Dented  
With Paint Damage



11: Tailgate  
Scratched  
Over 25mm Thru Paint



12: Bumper Rear  
Scratched  
Over 100mm Thru Paint



13: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint



14: Wheel osr  
Scratched  
Over 50mm



15: Door osr  
Chipped  
1 To 5



16: Door osf  
Chipped  
Edge Chip



17: Wing osf  
Scratched  
UpTo 25mm Thru Paint



18: Wheel osf  
Scratched  
Over 50mm



19: A Post os  
Scratched  
Over 25mm Thru Paint



20: Glass Roof  
Scratched  
Over 30mm

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK