

# VEHICLE INSPECTION REPORT

**SM67ULZ**

## Mini Countryman 1.5 Cooper S E ALL4 PHEV 5dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama  
GRADE  
**2**

### Details

Reg. date	09/02/2018	Body Style	Hatchback	Last service miles	65,606
Year	2018	Keys	2	MOT Due	27/02/2027
Mileage	72,853 Miles Warranted	Service history	Yes	Gearbox	Automatic
Fuel Type	Hybrid Electric	Service documents	Electronic / Online	Gears	6
Colour	GREEN	Number of stamps	4	Doors	5
VIN	WMWYU720303E34991	Last service date	24/04/2025		

Last Service - 24.04.2025 at 65606 miles (4 services) Type 2 charging cable

### Tyres

NSF	RAPID	5.0mm
NSR	FALKEN	5.0mm
OSF	HANKOOK	5.0mm
OSR	FALKEN	5.0mm
Spare		

## Features


- Bluetooth connection
- PAS
- Steering wheel mounted controls
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- Rear parking sensor
- Digital radio
- Roof rails
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Leather seat trim
- Front parking sensor
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Navigation system
- Service indicator
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5



2: Bumper Front  
Scratched  
25 to 100mm Thru Paint



3: Wing nsf  
Scratched  
UpTo 25mm Thru Paint



4: Door nsf  
Scratched  
Over 25mm Thru Paint



5: Door nsr  
Scratched  
UpTo 25mm Thru Paint



6: Wheel osr  
Scratched  
Up To 50mm



7: Door osr  
Scratched  
UpTo 25mm Thru Paint



8: Door osf  
Chipped  
1 To 5



9: Screen Front  
Chipped  
UpTo 10mm

**Interior**

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

**Vehicle Inspection Report**

**Disclaimer**

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK