



VEHICLE INSPECTION REPORT

WF15UUH

Volkswagen Polo 1.0 SE Design 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	30/03/2015	Body Style	Hatchback	Last service miles	46,038
Year	2015	Keys	2	MOT Due	29/03/2026
Mileage	49,644 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	5
Colour	BLUE	Number of stamps	8	Doors	5
VIN	WVWZZZ6RZFY203997	Last service date	29/08/2024		

£65 ADDITIONAL FEE Last service 29/08/2024 @ 46038 miles (8 SERVICES 4 MAIN DEALER)

Tyres


NSF	BUDGET	4.0mm
NSR	BUDGET	4.0mm
OSF	BUDGET	4.0mm
OSR	BUDGET	4.0mm
Spare		

Features


- Rear wiper
- Electric door mirrors
- Solid Paint
- Traction control
- Cloth seat trim
- Telephone
- Air conditioning
- ABS
- Tyre pressure monitor
- Alloy wheels
- Radio/CD
- Front electric windows
- Drivers airbag
- Central locking
- Body coloured bumpers
- Rear electric windows
- Passenger airbag
- Remote central locking

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5




2: Bumper Front
Scratched
Over 25mm Not Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Dented
Over 2 UpTo 10mm



5: Door nsf
Scratched
Over 25mm Not Thru Paint



6: Door nsr
Scratched
Over 25mm Not Thru Paint



7: Wheel nsr
Scratched
Over 50mm



8: Bumper Rear
Scratched
25 to 100mm Thru Paint



9: Wheel osr
Scratched
Up To 50mm

No Image

10: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint

No Image

11: Door osr
Scratched
Over 25mm Not Thru Paint

No Image

12: Door osf
Scratched
Over 25mm Not Thru Paint



13: Wheel osf
Scratched
Over 50mm



14: Carpets Front
Holed
Over 3mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK