



# VEHICLE INSPECTION REPORT

**YD19XRW**

## Vauxhall Grandland X 1.2 Turbo Elite Nav 5dr Auto [8 Speed]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama  
GRADE  
**3**

### Details

Reg. date	13/03/2019	Body Style	Hatchback	Last service miles	48,974
Year	2019	Keys	2	MOT Due	16/10/2026
Mileage	54,625 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Petrol	Service documents	Service Book	Gears	8
Colour	GREY	Number of stamps	6	Doors	5
VIN	W0VZRHNS0KS104250	Last service date	08/09/2025		

£90 ADDITIONAL FEE.

Last Service - 08.09.2025 at 48974 miles (6 main dealer services) Intermittent EML light on car has been plugged in and detects combustion misfire in cylinder 3

### Tyres

NSF	MAZZINI	5.0mm
NSR	CONTINENTAL	5.0mm
OSF	MAZZINI	5.0mm
OSR	CONTINENTAL	5.0mm
Spare		

## Features


- Bluetooth connection
- Telephone
- Fixed panoramic glass roof
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Cruise control
- Radio/CD
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Navigation system
- Body coloured bumpers
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Rear wiper
- Electric door mirrors
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5



2: Bumper Front Grill  
Broken  
Replace



3: Bumper Front  
Scratched  
25 to 100mm Thru Paint



4: Wheel nsf  
Scratched  
Over 50mm



5: Door nsf  
Dented  
Between 10mm + 30mm



6: Door nsf  
Chipped  
1 To 5



7: Door nsr  
Scratched  
Over 25mm Thru Paint




8: Qtr Panel nsr  
Chipped  
1 To 5



9: Wheel nsr  
Scratched  
Over 50mm



10: Bumper Rear  
Scratched  
25 to 100mm Thru Paint



11: Door nsr  
Chipped  
1 To 5



12: Door osf  
Dented  
Between 10mm + 30mm



13: Wing osf  
Chipped  
1 To 5



14: Wheel osf  
Scratched  
Over 50mm



15: Tailgate  
 Scratched  
 Over 25mm Thru Paint

**Interior**

<b>Carpet Condition</b>	Average	<b>Upholstery Condition</b>	Average
<b>Seat Condition</b>	Average	<b>Odour</b>	No

**Vehicle Inspection Report**

**Disclaimer**

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		