



VEHICLE INSPECTION REPORT

ND61XDG

Volkswagen Tiguan 2.0 TDi BlueMotion Tech SE 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	25/01/2012	Body Style	Estate	Last service miles	105,521
Year	2012	Keys	2	MOT Due	03/03/2027
Mileage	113,994 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Service Book	Gears	6
Colour	BLUE	Number of stamps	11		
VIN	WVGZZZ5NZCW053955	Last service date	27/02/2025		

£100 ADDITIONAL FEE

Last service 27/02/2025 at 105,521 miles- 11 services (4 main dealer) Parking sensors do not work

Tyres

NSF	BUDGET	5.0mm
NSR	BUDGET	3.0mm
OSF	BUDGET	5.0mm
OSR	BUDGET	3.0mm
Spare		


Features

- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Cruise control
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Front parking sensor
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim

Photos



Condition Check



Damage Photos



1: Wing osf
Chipped
1 To 5



2: Wing osf
Scratched
Over 25mm Not Thru Paint




3: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Not Thru Paint



4: Door osf
Chipped
Multiple Chips




5: Door osr
Chipped
1 To 5



6: Door osr
Scratched
Over 25mm Not Thru Paint



7: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



8: Tailgate
Dented
Over 30mm



9: Bumper Rear Moulding
Broken
Replace



10: Bumper Rear
Dented
Over 30mm



11: Qtr Panel nsr
Dented
With Paint Damage



12: Door nsr
Dented
Between 10mm + 30mm



13: Door nsf
Scratched
Over 25mm Not Thru Paint



14: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Not Thru Paint



15: Bumper Front Grill
Broken
Replace



16: Bonnet
Scratched
Over 25mm Thru Paint



17: Roof
Chipped
1 To 5

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK