

VEHICLE INSPECTION REPORT

AR23EKB

Ford Fiesta TITANIUM X TURBO M

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
1

Details

Reg. date	17/03/2023	Body Style	Hatchback	Last service miles	17,453
Year	2023	Keys	2	MOT Due	16/03/2027
Mileage	18,173 Miles Warranted	Service history	Yes	Gearbox	Manual
Fuel Type	Petrol	Service documents	Printout	Doors	5
Colour	BLUE	Number of stamps	2		
VIN	WF0JXXGAHJNG01564	Last service date	12/03/2026		

Last service 12/03/2026 at 17,453 miles- 2 services Some panels will require machine polish

Tyres



NSF	DAVANTI	Damaged
NSR	CONTINENTAL	5.0mm
OSF	CONTINENTAL	4.0mm
OSR	CONTINENTAL	5.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Heated front seat
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Leather seat trim
- Navigation system
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Alloy wheels
- Park assist camera
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Door osf
Chipped
1 To 5



2: Door osr
Chipped
1 To 5



3: Wheel nsf
Scratched
Over 50mm



4: Wheel nsf
Scratched
Over 50mm



5: Tyre nsf
Damaged
Replace



6: Bumper Front
Scratched
UpTo 25mm Thru Paint

Interior

Carpet Condition OK
Seat Condition OK

Upholstery Condition OK
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK