

VEHICLE INSPECTION REPORT

CE09OCU

Ford Focus 1.6 Zetec S 5dr

nama
GRADE
2

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	01/03/2009	Body Style	Hatchback	Last service miles	70,014
Year	2009	Keys	2	MOT Due	20/12/2026
Mileage	108,129 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	5
Colour	SILVER	Number of stamps	9	Doors	5
VIN	WF0PXXGCDP8S05222	Last service date	23/05/2018		

LAST SERVICE 23/05/2018 @ 70,014 MILES (9 SERVICES 3 MAIN DEALER)

Tyres

NSF	BUDGET	5.0mm
NSR	BUDGET	4.0mm
OSF	GT RADIAL	5.0mm
OSR	APTANY	4.0mm

Spare

Features


- Bluetooth connection
- Body coloured bumpers
- Front electric windows
- Drivers airbag
- Remote central locking
- Rear wiper
- Electric door mirrors
- Rear headrests
- Passenger airbag
- Cloth seat trim
- Telephone
- Air conditioning
- Metallic Paint
- Traction control
- Alloy wheels
- Radio/CD
- Front armrest
- ABS
- Central locking

Photos





Condition Check



Damage Photos



1: Wheel osf
Corroded
Light



2: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Not Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Door nsf
Chipped
1 To 5



5: Bumper Rear
Poor Previous Repair
Poor Paint



6: Bonnet
Chipped
1 To 5

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK