

VEHICLE INSPECTION REPORT

DS22JCJ

Vauxhall Corsa 1.2 SE Edition 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
2

Details

Reg. date	31/05/2022	Body Style	Hatchback	Last service miles	32,718
Year	2022	Keys	2	MOT Due	26/03/2027
Mileage	33,865 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	5
Colour	WHITE	Number of stamps	3	Doors	5
VIN	VXKUPHMHDN4245435	Last service date	16/03/2026		

Last Service - 16.03.2026 at 32718 miles (3 services) Some panels will require machine polish

Tyres

NSF	BUDGET	5.0mm
NSR	NEXEN	5.0mm
OSF	FARROAD	5.0mm
OSR	SUNNY	5.0mm
Spare		

Features


- Bluetooth connection
- Telephone
- Air conditioning
- Rear headrests
- Passenger airbag
- Remote central locking
- Cruise control
- Radio/CD
- Climate control
- Solid Paint
- Traction control
- Cloth seat trim
- Navigation system
- Body coloured bumpers
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Rear wiper
- Electric door mirrors
- Rear electric windows
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Door osf
Dented
Between 10mm + 30mm



3: Door osf
Chipped
Edge Chip



4: Qtr Panel osr
Dented
Between 10mm + 30mm



5: Bumper Rear
Scratched
25 to 100mm Thru Paint



6: Door nsr
Chipped
1 To 5



7: Door nsf
Chipped
1 To 5



8: Wing nsf
Dented
2 Or Less Up To 10mm




9: Wheel nsf
Scratched
Over 50mm



10: Bumper Front
Scratched
25 to 100mm Thru Paint



11: Bonnet
Chipped
1 To 5



12: Seat Base Cover nsf
Holed
UpTo 3mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK