



# VEHICLE INSPECTION REPORT

**LV67COJ**

## Nissan Qashqai 1.2 DiG-T Tekna 5dr Xtronic

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama  
GRADE  
**4**

### Details

Reg. date	29/09/2017	Body Style	Hatchback	Last service miles	30,959
Year	2017	Keys	2	MOT Due	Expired
Mileage	65,364 Miles Warranted	Service history	Yes	Gearbox	CVT
Fuel Type	Petrol	Service documents	Printout	Gears	1
Colour	GREY	Number of stamps	1	Doors	5
VIN	SJNFEAJ11U2035515	Last service date	30/05/2022		

### £90 ADDITIONAL FEE

Last service 30/05/2022 at 30,959 miles- 1 main dealer service  
MOT expired Some panels will require machine polish  
Bonnet will not open

### Tyres

NSF	BUDGET	3.0mm
NSR	ACCELERA	4.0mm
OSF	BUDGET	3.0mm
OSR	EVENT	4.0mm
Spare		

## Features


- Bluetooth connection
- Navigation system
- Telephone
- Fixed panoramic glass roof
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Cruise control
- Park assist camera
- Radio/CD
- Air conditioning
- Front electric windows
- ABS
- Tyre pressure monitor
- Leather seat trim
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Climate control
- Rear electric windows
- Drivers airbag
- Central locking
- Alloy wheels
- Heated front seat
- Rear wiper
- Electric door mirrors
- Electrically adjustable drivers seat
- Rear headrests
- Passenger airbag
- Remote central locking

## Photos





## Condition Check



## Damage Photos



1: Wheel osf  
Scratched  
Over 50mm



2: Wing osf  
Chipped  
1 To 5



3: Door osf  
Scratched  
Over 25mm Thru Paint



4: Door osr  
Dented  
2 Or Less Up To 10mm



5: Door osr  
Chipped  
1 To 5



6: Wheel osr  
Scratched  
Over 50mm



7: Bumper Rear  
Poor Previous Repair  
Paint Flake



8: Qtr Panel nsr  
Dented  
With Paint Damage



9: Door nsr  
Dented  
With Paint Damage



10: Wheel nsr  
Scratched  
Over 50mm



11: Door nsf  
Chipped  
Multiple Chips



12: Wheel nsf  
Scratched  
Over 50mm

### Interior

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		