



VEHICLE INSPECTION REPORT

LV20AHO

Renault ZOE 100kW i Iconic R135 50kWh 5dr Auto

| Inspection | | Vehicle | |
|-----------------|----|---------|--------|
| Serious Damage? | No | VAT | Margin |
| | | V5 | TBC |



Details

| | | | | | |
|------------|------------------------|--------------------|--------------|-------------|-----------|
| Reg. date | 19/06/2020 | Keys | 2 | CAP Clean | £7,550.00 |
| Year | 2020 | Service history | Yes | CAP Average | £6,600.00 |
| Mileage | 24,558 Miles Warranted | Service documents | Service Book | CAP Below | £5,625.00 |
| Fuel Type | Electric | Number of stamps | 4 | Gearbox | AUTOMATIC |
| Colour | BLUE | Last service date | 03/06/2024 | Gears | 1 |
| VIN | VF1AG000964867820 | Last service miles | 19,896 | Doors | 5 |
| Body Style | Hatchback | MOT Due | 07/05/2026 | | |

£100 ADDITIONAL FEE NO V5 Last service 03/06/2024 @ 19896 miles (4 MAIN DEALER SERVICES)
BATTERY OWNED

Tyres

| | | |
|-------|----------|-------|
| NSF | BUDGET | 6.0mm |
| NSR | MICHELIN | 5.0mm |
| OSF | BUDGET | 5.0mm |
| OSR | FARROAD | 5.0mm |
| Spare | | |

Features


- Bluetooth connection
- Telephone
- Air conditioning
- Metallic Paint
- Traction control
- Cloth seat trim
- Cruise control
- Radio/CD
- Climate control
- ABS
- Tyre pressure monitor
- Alloy wheels
- Navigation system
- Body coloured bumpers
- Front electric windows
- Drivers airbag
- Central locking
- Rear wiper
- Electric door mirrors
- Rear headrests
- Passenger airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Wheel nsf
Scratched
Over 50mm



2: Bumper Rear
Scratched
Over 25mm Not Thru Paint



3: Bumper Front
Scratched
25 to 100mm Thru Paint

4: Bonnet
Chipped
1 To 5

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

| | | | |
|--------------------------|----|--|----|
| Engine Runs | OK | Gearbox 1st and Reverse Test | OK |
| Brakes | OK | Clutch Slip Test from Static | OK |
| Parking Brake | OK | Gearbox Static Gear Selection (engine running) | OK |
| | | No Excessive Smoking | OK |
| EML light illuminated | OK | Oil warning light illuminated | OK |
| Airbag light illuminated | OK | Service indicator light illuminated | OK |
| ABS light illuminated | OK | | |
| Windows | OK | Radio | OK |
| Sat nav | OK | Steering | OK |