

## **VEHICLE INSPECTION REPORT**



## Suzuki Ignis 1.2 Dualjet 12V Hybrid SZ3 5dr

Inspection		Vehicle			nama
Serious Damage?	No	VAT	Margin		Grap Grap
		V5	Present		
Details					
Reg. date	20/11/2020	Keys	1	CAP Clean	£8,175.00
Year	2020	Service history	Yes	CAP Average	£7,200.00
Mileage	42,112 Miles Warranted	Service documents	Service Book	CAP Below	£6,200.00
		Number of stamps	4	Gearbox	MANUAL
Fuel Type	Hybrid Electric	Last service date	26/11/2024	Gears	5
Colour	RED	Last service miles	37,861	Doors	5
VIN	JSAMFH91S00102395	MOT Due	26/11/2025		
Body Style	Hatchback				

## Last service 26/11/2024 @ 37861 miles (4 MAIN DEALER SERVICES)

Tyres	
NOF	

NSF	BUDGET	3.0mm	
NSR	BUDGET	2.0mm	
OSF	BUDGET	4.0mm	
OSR	BUDGET	4.0mm	
Spare			

#### **Features**

- Bluetooth connection
- · Audio remote control
- Air conditioning
   Height adjustable drivers seat
   Curtain airbags
   Traction control

- Steel wheels


- PAS
- Radio/CD
- Climate control
- Solid Paint
- Isofix child seat anchor points
- Central locking
- · Rear wiper
- Body coloured bumpers
- Front electric windows
  3x3 point rear seat belts
- Passenger airbag
  Remote central locking
- Steering wheel mounted controls
   Electric door mirrors
- Front head restraints
- ABSSide airbags
- Cloth seat trim

#### **Photos**










## **Condition Check**



## **Damage Photos**



1: Bonnet Scratched Over 25mm Not Thru Paint



2: Bumper Front Cracked UpTo 25mm

# No Image

3: Wing nsf Scratched Over 25mm Not Thru Paint



Scratched Over 25mm Thru Paint



5: Door nsr Dented With Paint Damage



6: Qtr Panel nsr Dented Over 30% Of Panel



7: Bumper Rear Scratched Over 100mm Thru Paint



8: Door osr Scratched UpTo 25mm Thru Paint



9: Door osf Scratched Over 25mm Not Thru Paint



10: Wing osf Scratched Over 25mm Thru Paint

#### Interior

Carpet ConditionAverageUpholstery ConditionAverageSeat ConditionAverageOdourNo

### **Vehicle Inspection Report**

#### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting Ok		Gearbox Static Gear Selection (engine running)	
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
		, , , , , , , , , , , , , , , , , , ,	
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK