



# VEHICLE INSPECTION REPORT

**GN18ONW**

## Abarth 595 1.4 T-Jet 145 3dr

nama  
 GRADE  
**3**

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

### Details

Reg. date	26/05/2018	Body Style	Hatchback	Last service miles	45,955
Year	2018	Keys	2	MOT Due	04/10/2026
Mileage	46,564 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	5
Colour	RED	Number of stamps	7	Doors	3
VIN	ZFA312000J891568	Last service date	26/09/2025		

Last service 26/09/2025 at 45,955 miles- 7 services  
 Cambelt replaced 1/10/24 at 40,632 miles Some panels need machine polish  
 Breaks are binding

### Tyres

NSF	ROADSTONE	5.0mm
NSR	TRIANGLE	5.0mm
OSF	ROADSTONE	5.0mm
OSR	TRIANGLE	5.0mm
Spare		

## Features


- Bluetooth connection
- Digital radio
- Folding rear seats
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- PAS
- Body coloured bumpers
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Rear wiper
- Electric door mirrors
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Steering wheel mounted controls
- Air conditioning
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Bumper Front  
Scratched  
25 to 100mm Thru Paint



3: Wheel nsf  
Scratched  
Up To 50mm



4: Wing nsf  
Chipped  
1 To 5



5: Qtr Panel nsr  
Chipped  
1 To 5



6: Qtr Panel osr  
Dented  
Over 30mm



7: Door osf  
Chipped  
Edge Chip



8: Door osf  
Scratched  
Up To 25mm Thru Paint



9: Wing osf  
Chipped  
1 To 5

10: Roof  
Dented  
Over 30mm

**Interior**

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

**Vehicle Inspection Report**

**Disclaimer**

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK