



VEHICLE INSPECTION REPORT

SG59XHC

Volkswagen Touran 1.9 TDI DPF BlueMotion S 105 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
5

Details

Reg. date	30/09/2009	Body Style	MPV	Last service miles	164,746
Year	2009	Keys	2	MOT Due	08/08/2026
Mileage	167,876 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Printout	Gears	6
Colour	GREY	Number of stamps	10		
VIN	WVGZZZ1TZA030130	Last service date	01/08/2025		

£100 ADDITIONAL FEE

Last service 01/08/2025 at 164,746 miles- 10 services. Book
 Cambelt replaced 22/08/2018 at 110,015 miles

Tyres



NSF	BUDGET	5.0mm
NSR	BUDGET	6.0mm
OSF	MICHELIN	2.0mm
OSR	BUDGET	6.0mm
Spare		

Features


- Cruise control
- Electric door mirrors
- Rear headrests
- Passenger airbag
- Cloth seat trim
- Rear wiper
- Air conditioning
- Metallic Paint
- Traction control
- Steel wheels
- Radio/CD
- Climate control
- ABS
- Central locking
- Body coloured bumpers
- Front electric windows
- Drivers airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wing nsf
Dented
Between 10mm + 30mm



4: Wing nsf
Scratched
UpTo 25mm Thru Paint



5: Door nsr
Poor Previous Repair
Rippled UpTo 30%



6: Door nsr
Scratched
Over 25mm Thru Paint



7: Qtr Panel nsr
Rusted
Over 5mm



8: Bumper Rear
Scratched
Over 100mm Thru Paint



9: Tailgate
Dented
Over 30mm



10: Qtr Panel osr
Dented
With Paint Damage



11: Sill os
Dented
With Paint Damage



12: Door osr
Dented
Between 10mm + 30mm



13: Door osr
Scratched
Over 25mm Thru Paint



14: Door osf
Dented
Between 10mm + 30mm



15: Wing osf
Chipped
Edge Chip



16: Bumper Front
Insecure
Action Required



17: B Post os
Dented
Between 10mm + 30mm



18: Carpets Front
Holed
Over 3mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK