



VEHICLE INSPECTION REPORT

LS64LSJ

Toyota Aygo 1.0 VVT-i X-Clusiv 5dr x-shift

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	10/10/2014	Keys	1	CAP Clean	£6,800.00
Year	2014	Service history	Yes	CAP Average	£5,950.00
Mileage	20,959 Miles Warranted	Service documents	Service Book	CAP Below	£5,100.00
Fuel Type	Petrol	Number of stamps	5	Gearbox	CVT
Colour	BLACK	Last service date	03/05/2023	Gears	5
VIN	JTDKGNEC00N023933	Last service miles	17,135	Doors	5
Body Style	Hatchback	MOT Due	02/05/2026		

Last Service - 03.05.2023 at 17135 miles (5 services)

Tyres

NSF	BUDGET	5.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	5.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Rear headrests
- Passenger airbag
- Remote central locking
- Front parking sensor
- Telephone
- Air conditioning
- Metallic Paint
- Traction control
- Cloth seat trim
- Park assist camera
- Radio/CD
- Climate control
- ABS
- Tyre pressure monitor
- Alloy wheels
- Rear parking sensor
- Body coloured bumpers
- Front electric windows
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Door osf
Scratched
Over 25mm Not Thru Paint



3: Door osr
Scratched
Over 25mm Thru Paint



4: Wheel osr
Scratched
Over 50mm



5: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



6: Bumper Rear
Scratched
Up To 25mm Thru Paint



7: Wheel nsr
Corroded
Light



8: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



9: Door nsr
Scratched
Over 25mm Not Thru Paint



10: Door nsf
Dented
Over 2 UpTo 10mm



11: Door nsf
Scratched
Over 25mm Not Thru Paint




12: Wing nsf
Poor Previous Repair
Poor Paint



13: Wheel nsf
Scratched
Over 50mm



14: Bumper Front
Scratched
25 to 100mm Thru Paint



15: Bonnet
Scratched
Over 25mm Not Thru Paint

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK