



VEHICLE INSPECTION REPORT

GY20UVD

Audi Q7 45 TDI Quattro S Line 5dr Tiptronic

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	24/07/2020	Body Style	Estate	Last service miles	60,556
Year	2020	Keys	2	MOT Due	25/07/2026
Mileage	63,587 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Diesel	Service documents	Printout	Gears	8
Colour	SILVER	Number of stamps	3		
VIN	WAUZZZ4MXLD004209	Last service date	06/01/2026		

£90 ADDITIONAL FEE.

Last service 06/01/2026 at 60556 miles (3 main dealer services).

Tyres

NSF	GOODYEAR	6.0mm
NSR	GOODYEAR	6.0mm
OSF	GOODYEAR	6.0mm
OSR	GOODYEAR	6.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Electric door mirrors
- Electrically adjustable drivers seat
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Central locking
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Electrically adjustable passenger seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Remote central locking
- Front parking sensor
- PAS
- Digital radio
- Roof rails
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Leather seat trim
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Traction control
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wing nsf
Scratched
Over 25mm Thru Paint



4: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



5: Door nsf
Chipped
Edge Chip



6: Door nsr
Scratched
Over 25mm Thru Paint



7: Door Moulding nsr
Missing
Replace



8: Qtr Panel Arch Extension ns
Scratched (Painted)
UpTo 25mm Thru Paint



9: Bumper Rear
Scratched
Over 100mm Thru Paint



10: Bumper Reflector osr
Broken
Replace



11: Qtr Panel Arch Extension os
Scratched (Painted)
Over 25mm Thru Paint



12: Door osr
Dented
With Paint Damage




13: Door Moulding osr
Missing
Replace




14: Door osf
Scratched
Over 25mm Thru Paint



15: Wing of
Scratched
Up To 25mm Thru Paint



16: Screen Front
Chipped
Up To 10mm



17: Roof
Chipped
Edge Chip

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Turbo Boosting	OK	No Excessive Smoking	OK
Parking Brake	OK		

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK