



VEHICLE INSPECTION REPORT

GK22AWO

Audi Q2 35 TFSI Sport 5dr S Tronic

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
2

Details

Reg. date	08/03/2022	Body Style	Estate	Last service miles	60,016
Year	2022	Keys	2	MOT Due	13/01/2027
Mileage	62,886 Miles Warranted	Service history	Yes	Gearbox	SEMI AUTO
Fuel Type	Petrol	Service documents	Printout	Gears	7
Colour	WHITE	Number of stamps	1		
VIN	WAUZZZGA7NA024665	Last service date	14/01/2026		

£90 ADDITIONAL FEE.

Last service 14/01/2026 at 60016 miles (1 service).

Tyres

NSF	HANKOOK	5.0mm
NSR	HANKOOK	5.0mm
OSF	NEXEN	6.0mm
OSR	HANKOOK	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Electric door mirrors
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Side airbags
- Alloy wheels
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Central locking
- Front parking sensor
- PAS
- Digital radio
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Remote central locking
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Rear electric windows
- Metallic Paint
- Passenger airbag
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Qtr Panel Arch Extension ns
Scratched (Painted)
Over 25mm Thru Paint



4: Door osr
Chipped
Edge Chip



5: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Thru Paint



6: Wing osf
Chipped
1 To 5

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK