



# VEHICLE INSPECTION REPORT

**LX67WYG**

## Audi Q3 2.0 TDI Quattro Black Edition 5dr S Tronic

nama  
 GRADE  
**2**

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

### Details

Reg. date	09/09/2017	Body Style	Estate	Last service miles	85,614
Year	2017	Keys	2	MOT Due	08/09/2026
Mileage	96,327 Miles Warranted	Service history	Yes	Gearbox	SEMI AUTO
Fuel Type	Diesel	Service documents	Printout	Gears	7
Colour	WHITE	Number of stamps	4		
VIN	WAUZZZ8U7JR008647	Last service date	20/03/2025		

£100 ADDITIONAL FEE.  
 LAST SERVICE 20/03/2025 @ 85,614 MILES (4 SERVICES, 2 MAIN DEALER)

### Tyres


NSF	PIRELLI	6.0mm
NSR	PIRELLI	6.0mm
OSF	PIRELLI	6.0mm
OSR	PIRELLI	6.0mm
Spare		

### Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Body coloured bumpers
- Space saver spare wheel
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Partial leather seat trim
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Electric door mirrors
- Air conditioning
- Front head restraints
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels
- Front parking sensor
- PAS
- Digital radio
- Front fog lights
- Folding rear seats
- Height adjustable drivers seat
- Metallic Paint
- Drivers airbag
- Central locking
- Heated front seat
- Rear parking sensor
- Radio/CD
- Roof rails
- Front armrest
- Rear electric windows
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking

### Photos





## Condition Check



## Damage Photos



1: Wheel osf  
Scratched  
Over 50mm



2: Door osf  
Chipped  
Edge Chip



3: Door osr  
Chipped  
1 To 5



4: Bumper Rear  
Chipped  
1 To 5



5: Wheel nsr  
Scratched  
Over 50mm



6: Door nsr  
Chipped  
1 To 5




7: Wheel nsf  
Scratched  
Over 50mm



8: Bumper Front  
Chipped  
Multiple Chips



9: Bonnet  
Chipped  
1 To 5



10: Screen Front  
Chipped  
Over 10mm

**Interior**

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

**Vehicle Inspection Report**

**Disclaimer**

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Turbo Boosting	OK	No Excessive Smoking	OK
Parking Brake	OK		
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK