



# VEHICLE INSPECTION REPORT

**SB02MEL**

## BMW 5 Series 520i MHT M Sport 5dr Step Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC



### Details

Reg. date	15/12/2022	Colour	BLACK	MOT Due	14/12/2025
Year	2022	VIN	WBA12BM070CM19947	Gearbox	AUTOMATIC
Mileage	28,526 Miles Warranted	Body Style	Estate	Gears	8
Fuel Type	Hybrid Electric	Keys	2		

£65 ADDITIONAL FEE.

### Tyres

NSF	GOODYEAR	4.0mm
NSR	PIRELLI	4.0mm
OSF	GOODYEAR	4.0mm
OSR	PIRELLI	5.0mm
Spare		

## Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Audio remote control
- Electric door mirrors
- Electrically adjustable passenger seat
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Auxiliary input socket
- Air conditioning
- Front armrest
- Rear armrest
- ABS
- Traction control
- Leather seat trim
- Front parking sensor
- PAS
- Telephone
- Digital radio
- Climate control
- Front electric windows
- Rear electric windows
- Drivers airbag
- Tyre pressure monitor
- Alloy wheels
- Heated front seat
- Rear parking sensor
- Trip computer
- Body coloured bumpers
- Electrically adjustable drivers seat
- Front head restraints
- Solid Paint
- Isofix child seat anchor points
- Central locking

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5



2: Bumper Front  
Scratched  
Over 100mm Thru Paint





3: Wing nsf  
Scratched  
UpTo 25mm Thru Paint

No Image

4: Wing nsf  
Scratched  
Over 25mm Not Thru Paint

No Image

No Image

5: Door Mirror Assy nsf  
Scratched (Painted)  
Over 25mm Not Thru Paint

6: Door nsf  
Scratched  
Over 25mm Not Thru Paint



7: Door nsf  
Chipped  
1 To 5

No Image

8: Door nsr  
Scratched  
Over 25mm Not Thru Paint

No Image



9: Qtr Panel nsr  
Scratched  
Over 25mm Not Thru Paint

10: Qtr Panel nsr  
Chipped  
1 To 5



11: Wheel nsr  
Scratched  
Over 50mm



12: Bumper Rear  
Scratched  
25 to 100mm Thru Paint

No Image

No Image

13: Bumper Rear  
Scratched  
Over 25mm Not Thru Paint

14: Boot Lid  
Scratched  
Over 25mm Not Thru Paint



15: Qtr Panel osr  
Chipped  
1 To 5




16: Wheel osr  
Scratched  
Over 50mm




17: Door osr  
Scratched  
Over 25mm Not Thru Paint



18: Door osf  
Chipped  
1 To 5



19: Door osf  
Scratched  
Over 25mm Not Thru Paint



20: Wing osf  
Scratched  
Over 25mm Not Thru Paint

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK