



VEHICLE INSPECTION REPORT

GU72YTA

Audi A3 35 TFSI S Line 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	28/09/2022	Body Style	Hatchback	Last service miles	53,099
Year	2022	Keys	2	MOT Due	27/09/2026
Mileage	53,150 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Printout	Gears	6
Colour	WHITE	Number of stamps	6	Doors	5
VIN	WAUZZZGY0PA015337	Last service date	10/04/2026		

£90 ADDITIONAL FEE

LAST SERVICE 10/04/2026 @ 53,099 MILES (6 SERVICES, ALL MAIN DEALER)

INTERMITANT EML LIGHT ON

Tyres


NSF	BRIDGESTONE	5.0mm
NSR	PIRELLI	5.0mm
OSF	PIRELLI	5.0mm
OSR	PIRELLI	5.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Digital radio
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Remote central locking
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Traction control
- Leather seat trim
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Tyre pressure monitor
- Alloy wheels
- Navigation system
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wing nsf
Chipped
1 To 5



4: Door nsf
Dented
Between 10mm + 30mm



5: Door nsr
Dented
Between 10mm + 30mm



6: Door nsr
Chipped
1 To 5



7: Qtr Panel nsr
Dented
Over 30mm



8: Door osr
Dented
Over 30mm



9: Door osf
Chipped
Edge Chip



10: Screen Front
Chipped
UpTo 10mm



11: Roof
Chipped
Edge Chip



12: Wing osf
Dented
Between 10mm + 30mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK