



# VEHICLE INSPECTION REPORT

**HF23NTC**

## Ford Ecosport 1.0 EcoBoost 125 ST-Line 5dr

nama  
 GRADE  
**3**

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

### Details

Reg. date	10/03/2023	Body Style	Hatchback	Last service miles	13,373
Year	2023	Keys	2	MOT Due	09/03/2027
Mileage	20,952 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Printout	Gears	6
Colour	GREY	Number of stamps	1	Doors	5
VIN	WF01XXERK1NR10724	Last service date	21/06/2024		

Last Service - 21.06.2024 at 13373 miles (1 main dealer services) Some panel require machine polish

### Tyres



NSF	PIRELLI	5.0mm
NSR	PIRELLI	5.0mm
OSF	PIRELLI	5.0mm
OSR	PIRELLI	5.0mm
Spare		

## Features


- Bluetooth connection
- PAS
- Digital radio
- Roof rails
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Side airbags
- Alloy wheels
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- Drivers airbag
- Central locking
- Navigation system
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Isofix child seat anchor points
- Remote central locking
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Passenger airbag
- Partial leather seat trim

## Photos






## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5



2: Bumper Front  
Chipped  
Multiple Chips



3: Wheel nsf  
Scratched  
Up To 50mm



4: Wing nsf  
Scratched  
Over 25mm Thru Paint



5: Door nsf  
Chipped  
Edge Chip



6: Door nsr  
Chipped  
1 To 5



7: Bumper Rear  
Scratched  
Up To 25mm Thru Paint



8: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint



9: Door osr  
 Scratched  
 UpTo 25mm Thru Paint

**Interior**

<b>Carpet Condition</b>	Average	<b>Upholstery Condition</b>	Average
<b>Seat Condition</b>	Average	<b>Odour</b>	No

**Vehicle Inspection Report**

---

**Disclaimer**

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK