



VEHICLE INSPECTION REPORT

GY68EKP

Skoda Karoq 1.0 TSI SE Nav Plus 5dr

nama
GRADE
2

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	05/10/2018	Body Style	Estate	Last service miles	29,688
Year	2018	Keys	2	MOT Due	14/11/2026
Mileage	33,844 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Printout	Gears	6
Colour	BLACK	Number of stamps	6		
VIN	TMBKP7NU2K2011596	Last service date	17/10/2025		

£90 ADDITIONAL FEE

Last service 17/10/2025 at 29,688 miles- 6 main dealer services Multiple panels require machine polish

Tyres

NSF	CONTINENTAL	4.0mm
NSR	CONTINENTAL	4.0mm
OSF	CONTINENTAL	4.0mm
OSR	CONTINENTAL	4.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Cruise control
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Front parking sensor
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Navigation system
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Wing osf
Chipped
1 To 5



2: Door osf
Scratched
UpTo 25mm Thru Paint



3: Other
N/A
N/A



4: Door osf
Chipped
Edge Chip



5: Door osr
Chipped
1 To 5



6: Door nsr
Chipped
1 To 5



7: Door nsf
Chipped
1 To 5



8: Bumper Front
Scratched
25 to 100mm Thru Paint



9: Bumper Front
Chipped
Multiple Chips



10: Qtr Panel osr
Dented
Between 10mm + 30mm



11: Door nsr
Dented
2 Or Less UpTo 10mm



12: Bonnet
Chipped
1 To 5

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK