



VEHICLE INSPECTION REPORT

SG66UZZ

BMW 3 Series 320d xDrive M Sport 4dr

nama
GRADE
3

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	09/09/2016	Body Style	Saloon	Last service miles	105,865
Year	2016	Keys	1	MOT Due	04/02/2027
Mileage	106,132 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Service Book	Gears	6
Colour	WHITE	Number of stamps	3	Doors	4
VIN	WBA8C92010K487898	Last service date	20/03/2026		

£100 ADDITIONAL FEE

LAST SERVICE 20/03/2026 @ 105,865 MILES (3 SERVICES, 2 MAIN DEALER - BOOK AND PRINT) Osr light is loose

Tyres

NSF	KUMHO	4.0mm
NSR	FALKEN	4.0mm
OSF	KUMHO	4.0mm
OSR	FALKEN	4.0mm
Spare		

Features


- Bluetooth connection
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Heated front seat
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Navigation system
- Body coloured bumpers
- Front armrest
- Solid Paint
- Traction control
- Leather seat trim
- Rear parking sensor
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Wing osf
Chipped
1 To 5



2: Door osf
Chipped
Edge Chip



3: Door osr
Chipped
Edge Chip



4: Bumper Rear
Poor Previous Repair
Poor Paint



5: Bumper Front
Chipped
Multiple Chips



6: Bonnet
Chipped
Multiple Chips



7: Roof
Chipped
1 To 5

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK