



WA52MFY

VEHICLE INSPECTION REPORT

Volkswagen Golf Mk4 E

nama
 GRADE
5

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	01/09/2002	Body Style	Hatchback	Last service miles	68,151
Year	2002	Keys	2	MOT Due	07/09/2026
Mileage	117,384 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	5
Colour	SILVER	Number of stamps	16	Doors	5
VIN	WVWZZZ1JZ3W152808	Last service date	23/08/2016		

Last Service - 23.08.2016 at 6815 miles (15 services) Exhaust blowing

Tyres


NSF	LAUFENN	4.0mm
NSR	LAUFENN	5.0mm
OSF	LAUFENN	3.0mm
OSR	LAUFENN	4.0mm
Spare		

Features


- PAS
- Electric door mirrors
- Rear headrests
- 3x3 point rear seat belts
- Side airbags
- Spare wheel
- Rear wiper
- Folding rear seats
- Steering wheel rake adjustment
- ABS
- Central locking
- Radio/Cassette
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Remote central locking
- Body coloured bumpers
- Height adjustable drivers seat
- Metallic Paint
- Passenger airbag
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Wing osf
Chipped
1 To 5



2: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint



3: Door osf
Chipped
Multiple Chips



4: Door osr
Chipped
Multiple Chips



5: Qtr Panel osr
Dented
With Paint Damage



6: Bumper Rear
Scratched
Over 100mm Thru Paint



7: Qtr Panel nsr
Dented
With Paint Damage



8: Sill ns
Dented
With Paint Damage



9: Door nsr
Dented
With Paint Damage



10: Door nsf
Dented
With Paint Damage



11: Wing nsf
Poor Previous Repair
Paint Flake



12: Bumper Front
Scratched
Over 100mm Thru Paint



13: Bonnet
Scratched
Over 25mm Thru Paint



14: Screen Front
Chipped
UpTo 10mm



15: Roof
Chipped
1 To 5

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK