



VEHICLE INSPECTION REPORT

HK66VYA

Nissan Pulsar 1.2 DiG-T Tekna 5dr Xtronic

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	31/01/2017	Body Style	Hatchback	Last service miles	84,075
Year	2017	Keys	2	MOT Due	30/01/2027
Mileage	85,075 Miles Warranted	Service history	Yes	Gearbox	CVT
Fuel Type	Petrol	Service documents	Service Book	Gears	1
Colour	BLUE	Number of stamps	9	Doors	5
VIN	VSKDDAC13U0086968	Last service date	07/01/2026		

Last Service - 07.01.2026 at 84075 miles (9 services)

Tyres


NSF	GOODYEAR	5.0mm
NSR	FALKEN	5.0mm
OSF	GOODYEAR	5.0mm
OSR	GOODYEAR	4.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Digital radio
- Space saver spare wheel
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Leather seat trim
- Cruise control
- PAS
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Heated front seat
- Rear parking sensor
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Navigation system
- Steering wheel mounted controls
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint



2: Bumper Front
Poor Previous Repair
Poor Paint



3: Wing nsf
Scratched
Over 25mm Thru Paint



4: Door nsf
Scratched
Over 25mm Thru Paint



5: Door nsr
Dented
With Paint Damage



6: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



7: Bumper Rear
Scratched
25 to 100mm Thru Paint



8: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint




9: Door osr
Dented
Over 30mm



10: Door osf
Dented
Between 10mm + 30mm



11: Door osf
Chipped
Multiple Chips




12: Roof
Chipped
1 To 5



13: Wheel osf
Scratched
Over 50mm



14: Wing osf
Chipped
1 To 5



15: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK