



VEHICLE INSPECTION REPORT

YB15BFZ

Nissan Qashqai 1.5 dCi Tekna 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	08/06/2015	Body Style	Hatchback	Last service miles	70,491
Year	2015	Keys	2	MOT Due	31/05/2026
Mileage	79,825 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Service Book	Gears	6
Colour	GREY	Number of stamps	7	Doors	5
VIN	SJNFAAJ11U1400285	Last service date	28/05/2024		

£100 ADDITIONAL FEE

Last service 28/05/2024 at 70,491 miles- 7 services (3 main dealer)

Tyres

NSF	SUNNY	5.0mm
NSR	SUNNY	5.0mm
OSF	SUNNY	5.0mm
OSR	SUNNY	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Electric door mirrors
- Electrically adjustable drivers seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Leather seat trim
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Fixed panoramic glass roof
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Tyre pressure monitor
- Alloy wheels
- Front parking sensor
- PAS
- Digital radio
- Roof rails
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Poor Previous Repair
Paint Flake



3: Wheel nsf
Scratched
Over 50mm



4: Door nsf
Chipped
1 To 5



5: Door nsr
Dented
With Paint Damage



6: Wheel nsr
Scratched
Over 50mm



7: Wheel osr
Scratched
Over 50mm



8: Qtr Panel osr
Dented
2 Or Less UpTo 10mm



9: Qtr Panel osr
Chipped
1 To 5



10: Door osr
Chipped
Over 5mm



11: Door osf
Chipped
1 To 5



12: Wing osf
Chipped
1 To 5



13: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		