



# VEHICLE INSPECTION REPORT

**SG13XNE**

## KIA PRO CEED 1.6 GDi SE EcoDynamics 3dr

### Inspection

### Vehicle

VAT	Margin
V5	Present

### Details

<b>Reg. date</b>	13/03/2013	<b>Body Style</b>	Hatchback	<b>MOT Due</b>	01/02/2027
<b>Year</b>	2013	<b>Service history</b>	Yes	<b>Gearbox</b>	MANUAL
<b>Mileage</b>	98,383 Miles Warranted	<b>Service documents</b>	Printout	<b>Gears</b>	6
<b>Fuel Type</b>	Petrol	<b>Number of stamps</b>	2	<b>Doors</b>	3
<b>Colour</b>	SILVER	<b>Last service date</b>	02/04/2020		
<b>VIN</b>	U5YHN313LEL001329	<b>Last service miles</b>	58,173		

Last service 02/04/2020 at 58,173 miles- 2 services

### Tyres

NSF
NSR
OSF
OSR
Spare