

# VEHICLE INSPECTION REPORT

**DN10GKX**

## Ford Fiesta 1.4 Titanium 5dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama  
GRADE  
**4**

### Details

Reg. date	14/05/2010	Body Style	Hatchback	Last service miles	13,996
Year	2010	Keys	2	MOT Due	14/10/2026
Mileage	30,481 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Petrol	Service documents	Service Book	Gears	4
Colour	SILVER	Number of stamps	3	Doors	5
VIN	WF0JXXGAJJAT88477	Last service date	15/08/2013		

£100 ADDITIONAL FEE

Last service 15/08/2013 at 13,996 miles- 3 services

### Tyres

NSF	MICHELIN	2.0mm
NSR	TOYO	6.0mm
OSF	TOYO	5.0mm
OSR	TOYO	5.0mm
Spare		

## Features


- Front parking sensor
- Radio/CD
- Climate control
- ABS
- Central locking
- Rear parking sensor
- Body coloured bumpers
- Front electric windows
- Drivers airbag
- Remote central locking
- Rear wiper
- Electric door mirrors
- Rear headrests
- Passenger airbag
- Cloth seat trim
- Telephone
- Air conditioning
- Metallic Paint
- Traction control
- Alloy wheels

## Photos





## Condition Check



## Damage Photos



1: Seat Back Cover osf  
Holed  
Over 3mm



2: Wheel osf  
Scratched  
Over 50mm



3: Wing osf  
Chipped  
1 To 5



4: Door osf  
Poor Previous Repair  
Poor Paint



5: Door osr  
Poor Previous Repair  
Poor Paint



6: Qtr Panel osr  
Poor Previous Repair  
Poor Paint



7: Wheel osr  
Scratched  
Up To 50mm



8: Bumper Rear  
Chipped  
1 To 5



9: Wheel nsr  
Scratched  
Over 50mm



10: Door nsr  
Chipped  
1 To 5



11: Door nsf  
Poor Previous Repair  
Poor Paint



12: Wing nsf  
Poor Previous Repair  
Poor Paint



13: Wheel nsf  
Scratched  
Over 50mm



14: Bonnet  
Poor Previous Repair  
Poor Paint



15: Bumper Front  
 Poor Previous Repair  
 Poor Paint

**Interior**

**Carpet Condition**  
**Seat Condition**

Average  
 Average

**Upholstery Condition**  
**Odour**

Average  
 No

**Vehicle Inspection Report**

**Disclaimer**

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK