



VEHICLE INSPECTION REPORT

WG68MYB

Audi A6 40 TDI S Line 5dr S Tronic

nama
 GRADE
2

| Inspection | | Vehicle | |
|-----------------|----|---------|---------|
| Serious Damage? | No | VAT | Margin |
| | | V5 | Present |

Details

| | | | | | |
|-----------|---------------------------|-------------------|------------|--------------------|------------|
| Reg. date | 21/11/2018 | Body Style | Estate | Last service miles | 36,141 |
| Year | 2018 | Keys | 2 | MOT Due | 17/05/2026 |
| Mileage | 85,273 Miles Warranted | Service history | Yes | Gearbox | SEMI AUTO |
| Fuel Type | Diesel | Service documents | Printout | Gears | 7 |
| Colour | GREY | Number of stamps | 2 | | |
| VIN | WAUZZZF22KN033627 | Last service date | 20/06/2023 | | |

£90 ADDITIONAL FEE

Last service 20/06/2023 at 36,141 miles- 2 services

Tyres

| | | |
|-------|-------|-------|
| NSF | NEXEN | 4.0mm |
| NSR | NEXEN | 1.8mm |
| OSF | NEXEN | 3.0mm |
| OSR | NEXEN | 1.8mm |
| Spare | | |

Features


- Bluetooth connection
- Navigation system
- Telephone
- Air conditioning
- Front electric windows
- ABS
- Tyre pressure monitor
- Leather seat trim
- Cruise control
- Park assist camera
- Radio/CD
- Climate control
- Rear electric windows
- Drivers airbag
- Central locking
- Alloy wheels
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Electrically adjustable drivers seat
- Rear headrests
- Passenger airbag
- Remote central locking
- Heated front seat
- Rear wiper
- Electric door mirrors
- Electrically adjustable passenger seat
- Metallic Paint
- Traction control
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Wheel osf
Scratched
Up To 50mm



2: Door osr
Chipped
1 To 5



3: Wheel osr
Scratched
Up To 50mm



4: Wheel nsr
Scratched
Over 50mm




5: Wheel nsf
Scratched
Over 50mm



6: Bumper Front
Chipped
Multiple Chips



7: Bonnet
Chipped
1 To 5



8: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

| | | | |
|--------------------------|----|--|----|
| Engine Runs | OK | Gearbox 1st and Reverse Test | OK |
| Brakes | OK | Clutch Slip Test from Static | OK |
| Turbo Boosting | OK | Gearbox Static Gear Selection (engine running) | OK |
| Parking Brake | OK | No Excessive Smoking | OK |
| EML light illuminated | OK | Oil warning light illuminated | OK |
| Airbag light illuminated | OK | DPF light illuminated | OK |
| ABS light illuminated | OK | Service indicator light illuminated | OK |
| Windows | OK | Radio | OK |
| Sat nav | OK | Steering | OK |