

VEHICLE INSPECTION REPORT

MA11GGP

Honda Jazz 1.2 i-VTEC S 5dr [AC]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	24/03/2011	Body Style	Hatchback	Last service miles	96,699
Year	2011	Keys	1	MOT Due	26/03/2027
Mileage	97,020 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	5
Colour	RED	Number of stamps	5	Doors	5
VIN	SHHGG5730CU001042	Last service date	24/03/2026		

Last Service - 24.03.2026 at 96699 miles (5 services)


Tyres

NSF	YOKOHAMA	5.0mm
NSR	FALKEN	5.0mm
OSF	YOKOHAMA	5.0mm
OSR	YOKOHAMA	5.0mm
Spare		

Features


- PAS
- Body coloured bumpers
- Front electric windows
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Steel wheels
- Rear wiper
- Electric door mirrors
- Front head restraints
- Solid Paint
- Drivers airbag
- Central locking
- Steering wheel mounted controls
- Air conditioning
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Radio/CD
- Folding rear seats
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Poor Previous Repair
Paint Flake



3: Wing nsf
Chipped
1 To 5



4: Door nsf
Scratched
Over 25mm Thru Paint



5: Door nsr
Scratched
Over 25mm Thru Paint



6: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



7: Bumper Rear
Poor Previous Repair
Paint Flake



8: Tailgate
Chipped
1 To 5



9: Qtr Panel osf
Dented
With Paint Damage



10: Door osf
Chipped
1 To 5



11: Door osf
Dented
Between 10mm + 30mm



12: Door osf
Scratched
Over 25mm Thru Paint



13: Wing osf
Scratched
Over 25mm Thru Paint



14: Roof
Chipped
1 To 5



15: Seat Back Cover nsf
Torn
Over 3mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK