

VEHICLE INSPECTION REPORT

GU22YDH

Vauxhall Vivaro 2700 1.5d 120PS Sportive H1 Van

Inspection		Vehicle	
Serious Damage?	No	VAT	VAT Qualifying
		V5	Buyer To Apply

nama
GRADE
4

Details

Reg. date	12/03/2022	VIN	VXEVBHVMN7008801	MOT Due	07/04/2027
Year	2022	Body Style	Panel Van	Gearbox	MANUAL
Mileage	36,003 Miles Warranted	Keys	2	Gears	6
Fuel Type	Diesel	Service history	Yes		
Colour	BLACK	Service documents	Printout		

NO V5

Last service 08/04/2026 at 35,994 miles- 3 services

MOT in 2025 recorded in KM on MOT history Near side rear door not closing properly


Tyres



NSF	FALKEN	4.0mm
NSR	CONTINENTAL	Damaged
OSF	BUDGET	5.0mm
OSR	CONTINENTAL	5.0mm
Spare		

Features


- Bluetooth connection
- Air conditioning
- Passenger airbag
- Cruise control
- Front electric windows
- Central locking
- Rear parking sensor
- Metallic Paint
- Cloth seat trim
- Digital radio
- Drivers airbag

Photos





Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Bumper Front Moulding
Scratched (Painted)
Over 25mm Thru Paint



4: Wing nsf
Scratched
Over 25mm Thru Paint



5: Door nsf
Scratched
UpTo 25mm Thru Paint



6: Door nsf
Scratched
Over 25mm Thru Paint



7: Door nsr
Dented
With Paint Damage



8: Qtr Panel nsr
Dented
With Paint Damage



9: Tailgate
Scratched
Over 25mm Thru Paint



10: Bumper Rear
Scratched
Over 100mm Thru Paint



11: Qtr Panel osr
Scratched
Over 25mm Thru Paint




12: Door osr
Scratched
Over 25mm Thru Paint



13: Door osf
Scratched
Over 25mm Thru Paint



14: Wing osf
Scratched
Over 25mm Thru Paint



15: Roof
 Scratched
 Over 25mm Thru Paint

16: Tyre nsr
 Damaged
 Replace

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK