

VEHICLE INSPECTION REPORT

HK56KXW

Peugeot 107 1.0 Urban 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
5

Details

Reg. date	31/01/2007	Body Style	Hatchback	Last service miles	132,821
Year	2007	Keys	2	MOT Due	17/12/2026
Mileage	135,132 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	5
Colour	RED	Number of stamps	12	Doors	5
VIN	VF3PNCFAC88117946	Last service date	10/01/2022		

Last service 10/01/2022 at 132,821 miles- 12 services. Book and print Some panels require machine polish


Tyres

NSF	YOKOHAMA	5.0mm
NSR	YOKOHAMA	5.0mm
OSF	YOKOHAMA	5.0mm
OSR	YOKOHAMA	5.0mm
Spare		

Features


- PAS
- Folding rear seats
- Steering wheel rake adjustment
- ABS
- Side airbags
- Steel wheels
- Rear wiper
- Front electric windows
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Radio/CD
- Front head restraints
- Solid Paint
- Isofix child seat anchor points
- Remote central locking
- Body coloured bumpers
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Seat Back Cover osr
Torn
Over 3mm



2: Bonnet
Dented
With Paint Damage



3: Bumper Front
Poor Previous Repair
Paint Flake



4: Front TowEye Cvr
Missing
Replace




5: Wing nsf
Scratched
Over 25mm Thru Paint



6: Sill ns
Dented
With Paint Damage



7: Door nsf
Dented
With Paint Damage



8: Door nsr
Scratched
Over 25mm Thru Paint



9: Bumper Rear
Poor Previous Repair
Paint Flake



10: Door osf
Scratched
Over 25mm Thru Paint



11: Sill os
Dented
Over 30mm



12: Door osf
Dented
Between 10mm + 30mm



13: Wing osf
Chipped
1 To 5



14: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint



15: Roof
Chipped
Edge Chip

16: Other
N/A
N/A

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK