



VEHICLE INSPECTION REPORT

GU14SUO

Skoda Yeti Outdoor 2.0 TDI CR [140] Elegance 4x4 5dr

nama
 GRADE
4

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	24/03/2014	Body Style	Hatchback	Last service miles	108,274
Year	2014	Keys	2	MOT Due	20/02/2027
Mileage	109,960 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Printout	Gears	6
Colour	GREEN	Number of stamps	6	Doors	5
VIN	TMBMD75L1E6026225	Last service date	27/01/2026		

Last service 27/01/2026 at 108,274 miles- 6 services
 Cambelt replaced 05/02/2021 at 56,141 miles Some panels will require machine polish

Tyres


NSF	LAUFENN	1.8mm
NSR	LAUFENN	3.0mm
OSF	LAUFENN	2.0mm
OSR	LAUFENN	2.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Alloy wheels
- Cruise control
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Central locking
- Front parking sensor
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Remote central locking
- Heated front seat
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Leather seat trim

Photos





Condition Check



Damage Photos



1: Wing osf
Poor Previous Repair
Poor Paint



2: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint



3: Door osf
Chipped
Edge Chip



4: Door osf
Dented
2 Or Less Up To 10mm



5: Door osr
Dented
Over 30mm



6: Bumper Rear
Scratched
25 to 100mm Thru Paint



7: Bumper Rear
Chipped
Multiple Chips



8: Qtr Panel nsr
Dented
Over 30mm



9: Wheel nsr
Corroded
Light



10: Door nsr
Chipped
Over 5mm



11: Door nsf
Dented
Over 30mm



12: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



13: Bumper Front
Poor Previous Repair
Poor Paint



14: Bonnet
Dented
With Paint Damage

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK