



VEHICLE INSPECTION REPORT

WJ11UOD

Skoda Octavia 2.0T FSI vRS 5dr

nama
 GRADE
2

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	11/03/2011	Body Style	Hatchback	Last service miles	51,875
Year	2011	Keys	2	MOT Due	07/09/2026
Mileage	59,357 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	6
Colour	GREY	Number of stamps	6	Doors	5
VIN	TMBEF21Z6B2109034	Last service date	15/07/2025		

£90 ADDITIONAL FEE.

LAST SERVICE 15/07/2025 @ 51,875 MILES (6 SERVICES, 3 MAIN DEALER)
 STAGE 1 MAP ON THE CAR.

Tyres

NSF	BRIDGESTONE	4.0mm
NSR	BRIDGESTONE	6.0mm
OSF	BRIDGESTONE	3.0mm
OSR	BRIDGESTONE	6.0mm


Spare

Features


- Bluetooth connection
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Alloy wheels
- Cruise control
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Park assist camera
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Leather seat trim

Photos





Condition Check



Damage Photos



1: Door osf
Chipped
1 To 5



2: Wheel osr
Scratched
Up To 50mm



3: Bumper Rear
Chipped
1 To 5



4: Qtr Panel nsr
Chipped
1 To 5



5: Door Moulding nsf
Scratched (Painted)
Over 25mm Thru Paint



6: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



7: Wing nsf
Chipped
1 To 5



8: Wheel nsf
Scratched
Over 50mm



9: Bumper Front
Chipped
Multiple Chips



10: Bumper Front
Scratched
25 to 100mm Thru Paint



11: Bonnet
Chipped
1 To 5



12: Spoiler Rear
Scratched (Painted)
UpTo 25mm Thru Paint

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK