

VEHICLE INSPECTION REPORT

GY63AJU

Kia Picanto 1.0 1 Air 5dr

Inspection		Vehicle			nama
Serious Damage?	No	VAT	Margin		GRADE
		V5	Present		
Details					
Reg. date	02/11/2013	Keys	2	CAP Clean	£2,350.00
Year	2013	Service history	Yes	CAP Average	£1,925.00
Mileage	55,150 Miles Warranted	Service documents	Service Book	CAP Below	£1,475.00
		Number of stamps	11	Gearbox	MANUAL
Fuel Type	Petrol	Last service date	30/10/2024	Gears	5
Colour	RED	Last service miles	52,448	Doors	 5
VIN	KNABE511LDT450009	MOT Due	14/11/2025		
Body Style	Hatchback		,,		

£100 ADDITIONAL FEE Last service 30/10/2024 @ 52448 miles (11 MAIN DEALER SERVICES) Gear linkage feels stiff

Т	٠	r	е	S
-	,	•	_	_

NSF	BUDGET	5.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	5.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Bluetooth connection
- Body coloured bumpers
- Metállic Paint
- · Steel wheels
- Traction control
- Rear wiper
- Air conditioning
- Central locking
- Telephone
- Front electric windows
- Drivers airbag Remote central locking
- Radio/CD
- · Rear headrests
- Passenger airbag
- Cloth seat trim

Photos










Condition Check



Damage Photos



1: Wing osf Dented 2 Or Less UpTo 10mm



2: Wing osf Chipped 1 To 5



3: Door osf Chipped 1 To 5



4: Door osf Chipped Edge Chip



5: Door osr Chipped Edge Chip



6: Bumper Rear Cracked Over 25mm



7: Qtr Panel nsr Dented With Paint Damage



8: Door nsf Chipped 1 To 5



9: Door nsr Scratched Over 25mm Thru Paint

Interior

Carpet ConditionAverageUpholstery ConditionAverageSeat ConditionAverageOdourNo

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake O		Gearbox Static Gear Selection (engine running)	
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
5 5		Service indicator light indiffinated	OIC
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK