



# VEHICLE INSPECTION REPORT

**EJ64NLN**

## Nissan Qashqai 1.6 dCi Tekna 5dr Xtronic

nama  
 GRADE  
**3**

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

### Details

Reg. date	16/01/2015	Body Style	Hatchback	Last service miles	74,578
Year	2015	Keys	2	MOT Due	15/01/2027
Mileage	79,208 Miles Warranted	Service history	Yes	Gearbox	CVT
Fuel Type	Diesel	Service documents	Printout	Gears	1
Colour	BLACK	Number of stamps	2	Doors	5
VIN	SJNFDAJ11U1292742	Last service date	27/08/2025		

£90 ADDITIONAL FEE.

LAST SERVICE 27/08/2025 @ 74,578 MILES (2 SERVICES) Multiple panels will require machine polish

### Tyres

NSF	BUDGET	2.0mm
NSR	TOYO	5.0mm
OSF	BUDGET	3.0mm
OSR	TOYO	5.0mm
Spare		

### Features


- Bluetooth connection
- Navigation system
- Telephone
- Fixed panoramic glass roof
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Cruise control
- Park assist camera
- Radio/CD
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Heated front seat
- Rear wiper
- Electric door mirrors
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim

### Photos





## Condition Check



## Damage Photos



1: Wheel osf  
Scratched  
Over 50mm



2: Wing osf  
Chipped  
1 To 5



3: Door osf  
Chipped  
Edge Chip



4: Door osr  
Chipped  
1 To 5



5: Wheel osr  
Scratched  
Over 50mm



6: Door osr  
Chipped  
Edge Chip



7: Bumper Rear  
Chipped  
Multiple Chips



8: Bumper Rear  
Scratched  
Up To 25mm Thru Paint



9: Lamp nsr  
Broken  
Replace



10: Qtr Panel nsr  
Scratched  
UpTo 25mm Thru Paint



11: Wheel nsr  
Scratched  
Up To 50mm



12: Door nsr  
Chipped  
1 To 5



13: Door nsf  
Chipped  
1 To 5



14: Wheel nsf  
Scratched  
Over 50mm



15: Bumper Front  
 Poor Previous Repair  
 Poor Paint

16: Bonnet  
 Chipped  
 1 To 5

**Interior**

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

**Vehicle Inspection Report**

**Disclaimer**

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		