



VEHICLE INSPECTION REPORT

YT65YJP

Citroen DS3 1.6 VTi DStyle Plus 2dr Auto

nama
 GRADE
3

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	18/09/2015	Body Style	Convertible	Last service miles	73,435
Year	2015	Keys	2	MOT Due	13/01/2027
Mileage	76,326 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Petrol	Service documents	Service Book	Gears	5
Colour	GREY	Number of stamps	9		
VIN	VF7SB5FS9FW544186	Last service date	12/01/2026		

Last Service - 12.01.2026 at 73435 miles (9 services) Exhaust blowing


Tyres

NSF	HIFLY	5.0mm
NSR	HIFLY	5.0mm
OSF	RAPID	5.0mm
OSR	HIFLY	5.0mm
Spare		

Features


- Bluetooth connection
- Radio/CD
- Air conditioning
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Cruise control
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- PAS
- Electric door mirrors
- Front armrest
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Rear parking sensor
- Front fog lights
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Chipped
Multiple Chips



3: Wheel nsf
Scratched
Over 50mm



4: Door nsf
Dented
With Paint Damage



5: Wheel nsr
Scratched
Over 50mm



6: Bumper Rear
Scratched
25 to 100mm Thru Paint



7: Qtr Panel osr
Scratched
Over 25mm Thru Paint



8: Wheel osr
Scratched
Over 50mm



9: Door osf
Dented
Between 10mm + 30mm



10: Door osf
Chipped
1 To 5



11: Wheel osf
Scratched
Over 50mm



12: Wing osf
Scratched
Over 25mm Thru Paint



13: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK