

46 Brampton Road Eastbourne **BN22 9BN** 01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

GX15ZNC

Citroen C4 Cactus 1.2 PureTech [82] Flair 5dr

Inspection		Vehicle			nama
Serious Damage?	No	VAT	Margin		Grade
		V5	Present		
Details					
Reg. date	23/03/2015	Body Style	Hatchback	CAP Below	£1,825.00
Year	2015	Keys	2	Gearbox	MANUAL
Mileage	67,162 Miles Warranted	Service history	None	Gears	5
		MOT Due	15/07/2025	Doors	5
Fuel Type	Petrol	CAP Clean	£2,800.00		
Colour	BLACK	CAP Average	£2,325.00		
VIN	VF70PHMZBFE510338		,		

No Service History Clutch High **Exhaust Blowing** EML Light On

Tyres

NSF	LAUFENN	4.0mm	
NSR	BUDGET	5.0mm	
OSF	BUDGET	4.0mm	
OSR	BUDGET	5.0mm	
Spare			

Features

- Bluetooth connection
- Rear wiper
- Electric door mirrors

- Front electric windowsDrivers airbagRemote central locking
- Navigation system ٠ Telephone
- Air conditioning
- Rear headrests
 Traction control
 Cloth seat trim

- Park assist camera ٠
- Radio/CD
- Climate control •
- Metallic Paint
 Tyre pressure monitor
 Alloy wheels
- Rear parking sensor Body coloured bumpers
- Front armrest
- ABS
- Central locking

Photos






















Condition Check



Damage Photos



1: Carpets Fro Holed Over 3mm

2: Wheel osf Scratched Over 50mm





3: Wing osf Chipped 1 To 5

4: Door osf Poor Previous Repair Paint Flake



5: Bumper Rear Scratched Over 25mm Not Thru Paint



6: Wheel nsr Scratched Up To 50mm



7: Wheel nsf Scratched Over 50mm

Interior

Eastbourne Car Auctions

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running	
		No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK