



VEHICLE INSPECTION REPORT

GY19YRL

Volkswagen Polo 1.0 TSI 115 R-Line 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	29/03/2019	Body Style	Hatchback	Last service miles	49,306
Year	2019	Keys	2	MOT Due	30/03/2027
Mileage	49,475 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Printout	Gears	6
Colour	BLACK	Number of stamps	6	Doors	5
VIN	WVVZZZAWZKU049446	Last service date	18/03/2026		

£90 ADDITIONAL FEE.

Last service 18/03/2026 at 18/03/2026 at 49,306 miles- 6 main dealer services Multiple panels will require machine polish

Tyres


NSF	WINDFORCE	5.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	4.0mm
OSR	MAXXIS	4.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Rear electric windows
- Drivers airbag
- Central locking
- Cruise control
- Telephone
- Air conditioning
- Rear headrests
- Passenger airbag
- Remote central locking
- Front parking sensor
- Radio/CD
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Rear parking sensor
- Body coloured bumpers
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Seat Back Cover nsf
Holed
UpTo 3mm



2: Door osf
Chipped
Edge Chip



3: Door osr
Chipped
1 To 5



4: Qtr Panel osr
Chipped
1 To 5



5: Bumper Rear
Scratched
25 to 100mm Thru Paint



6: Qtr Panel nsr
Chipped
1 To 5




7: Door nsr
Dented
Over 30mm




8: Door nsf
Dented
Over 30mm




9: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



10: Bonnet
Chipped
1 To 5



11: Bumper Front
Scratched
25 to 100mm Thru Paint



12: Boot Lid
Dented
Over 30mm



13: Qtr Panel osr
Dented
2 Or Less UpTo 10mm



14: Bumper Rear
Chipped
1 To 5



15: Seat Base Cover of
 Holed
 UpTo 3mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK