



VEHICLE INSPECTION REPORT

DF64HPY

Vauxhall Insignia 2.0 CDTi [163] ecoFLEX SRi Nav 5dr [Start Stop]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	06/01/2015	Body Style	Estate	Last service miles	106,883
Year	2015	Keys	2	MOT Due	05/01/2027
Mileage	109,523 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Printout	Gears	6
Colour	BLACK	Number of stamps	6		
VIN	W0LGS8EMXE1197214	Last service date	02/01/2026		

£90 ADDITIONAL FEE

LAST SERVICE 02/01/2026 @ 106,883 MILES (6 SERVICES, 5 MAIN DEALER) Multiple panels will require machine polish

Tyres

NSF	PIRELLI	4.0mm
NSR	PIRELLI	4.0mm
OSF	PIRELLI	4.0mm
OSR	PIRELLI	4.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Digital radio
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Tyre pressure monitor
- Alloy wheels
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Navigation system
- Steering wheel mounted controls
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Wing osf
Chipped
1 To 5



3: Door osf
Chipped
Edge Chip



4: Qtr Panel osr
Dented
With Paint Damage



5: Wheel osr
Scratched
Over 50mm



6: Bumper Rear
Dented
With Paint Damage



7: Tailgate
Scratched
Over 25mm Thru Paint



8: Wheel nsr
Scratched
Over 50mm



9: Qtr Panel nsf
Chipped
1 To 5



10: Door nsf
Chipped
Multiple Chips



11: Door nsf
Dented
With Paint Damage



12: Wing nsf
Scratched
Over 25mm Thru Paint




13: Wheel nsf
Scratched
Over 50mm



14: Bumper Front
Scratched
Over 100mm Thru Paint



15: Bonnet
Chipped
Multiple Chips



16: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK