



# VEHICLE INSPECTION REPORT

**BV67VFB**

## Mercedes-Benz C Class C220d Sport Premium 4dr 9G-Tronic

nama  
 GRADE  
**3**

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

### Details

Reg. date	30/09/2017	Body Style	Saloon	Last service miles	126,030
Year	2017	Keys	2	MOT Due	31/10/2026
Mileage	138,863 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Diesel	Service documents	Printout	Gears	9
Colour	GREY	Number of stamps	4	Doors	4
VIN	WDD2050042R302736	Last service date	07/06/2025		

Last service 07/06/2025 at 126030 miles (4 services (2 main dealer)).

### Tyres

NSF	BRIDGESTONE	2.5mm
NSR	PIRELLI	1.7mm
OSF	BRIDGESTONE	Damaged
OSR	PIRELLI	1.7mm
Spare		

### Features


- Bluetooth connection
- Navigation system
- Radio/CD
- Air conditioning
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim
- Cruise control
- Park assist camera
- Body coloured bumpers
- Climate control
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Front parking sensor
- Rear parking sensor
- Electric door mirrors
- Electrically adjustable drivers seat
- Rear electric windows
- Drivers airbag
- Central locking
- Heated front seat
- Telephone
- Electric sunroof
- Electrically adjustable passenger seat
- Rear headrests
- Passenger airbag
- Remote central locking

### Photos





## Condition Check



## Damage Photos



1: Wheel of  
Corroded  
Light



2: Tyre of  
Damaged  
Replace



3: Qtr Panel osr  
Dented  
Over 30mm



4: Wheel osr  
Corroded  
Light



5: Bumper Rear  
Scratched  
25 to 100mm Thru Paint



6: Wheel nsr  
Corroded  
Light



7: Door nsr  
Chipped  
1 To 5



8: Wing nsf  
Dented  
Over 30mm



9: Wheel nsf  
Corroded  
Light



10: Bumper Front  
Poor Previous Repair  
Poor Paint



11: Bonnet  
Chipped  
1 To 5



12: Other  
N/A  
N/A

### Interior

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		