



VEHICLE INSPECTION REPORT

GX65YFW

Kia Ceed 1.4 SR7 5dr

nama
 GRADE
3

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	11/09/2015	Body Style	Hatchback	Last service miles	66,422
Year	2015	Keys	2	MOT Due	14/09/2026
Mileage	70,021 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	6
Colour	WHITE	Number of stamps	10	Doors	5
VIN	U5YHM511LFL200790	Last service date	12/09/2025		

Last Service - 12.09.2025 at 6642 miles (10 services) Multiple panels will require machine polish

Tyres

NSF	BUDGET	Damaged
NSR	BUDGET	4.0mm
OSF	BUDGET	4.0mm
OSR	BUDGET	4.0mm
Spare		

Features


- Bluetooth connection
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- PAS
- Radio/CD
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Cloth seat trim
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Traction control
- Alloy wheels
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Central locking

Photos





Condition Check



Damage Photos



1: Wheel of
Scratched
Over 50mm



2: Door of
Chipped
Edge Chip



3: Other
N/A
N/A



4: Door osr
Chipped
1 To 5



5: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



6: Bumper Rear
Scratched
Over 100mm Thru Paint



7: Qtr Panel nsr
Dented
With Paint Damage



8: Door nsr
Chipped
1 To 5



9: Door nsf
Dented
2 Or Less UpTo 10mm



10: Door nsf
Chipped
Edge Chip




11: Wheel nsf
Scratched
Over 50mm



12: Wheel nsr
Scratched
Over 50mm



13: Bumper Front
Chipped
Multiple Chips



14: Bonnet
Chipped
1 To 5



15: Roof
Chipped
1 To 5

16: Tyre nsf
Damaged
Replace

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK