



# VEHICLE INSPECTION REPORT

**SH09KYV**

## MAZDA 3 1.6d TS 5dr

### Inspection

### Vehicle

VAT	Margin
V5	TBC

### Details

<b>Reg. date</b>	10/06/2009	<b>Colour</b>	SILVER	<b>Gearbox</b>	MANUAL
<b>Year</b>	2009	<b>VIN</b>	JMZBL14Y201108729	<b>Gears</b>	5
<b>Mileage</b>	111,000 Miles Warranted	<b>Body Style</b>	Hatchback	<b>Doors</b>	5
<b>Fuel Type</b>	Diesel	<b>MOT Due</b>	Expired		

### Tyres

NSF
NSR
OSF
OSR
Spare