

# VEHICLE INSPECTION REPORT

**HN62OHU**

## Toyota Aygo 1.0 VVT-i Fire 5dr [AC]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama  
GRADE  
**4**

### Details

Reg. date	29/11/2012	Body Style	Hatchback	Last service miles	38,143
Year	2012	Keys	2	MOT Due	17/02/2027
Mileage	117,706 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	5
Colour	WHITE	Number of stamps	4	Doors	5
VIN	JTDKG18C40N663938	Last service date	17/08/2018		

Last Service - 17.08.2018 at 38143 miles (4 services)

### Tyres

NSF	AVON	5.0mm
NSR	BUDGET	5.0mm
OSF	HANKOOK	5.0mm
OSR	BUDGET	5.0mm
Spare		

### Features


- PAS
- Air conditioning
- Rear headrests
- Passenger airbag
- Cloth seat trim
- Rear wiper
- Folding rear seats
- Metallic Paint
- Side airbags
- Alloy wheels
- Radio/CD
- Front electric windows
- ABS
- Central locking
- Body coloured bumpers
- Front head restraints
- Drivers airbag
- Remote central locking

### Photos





## Condition Check



## Damage Photos



1: Other  
N/A  
N/A



2: Bonnet  
Chipped  
Multiple Chips



3: Bumper Front  
Scratched  
25 to 100mm Thru Paint



4: Wheel nsf  
Scratched  
Over 50mm



5: Wing nsf  
Chipped  
1 To 5



6: Wing nsf  
Scratched  
Over 25mm Thru Paint



7: Door nsf  
Chipped  
Edge Chip



8: Door nsr  
Scratched  
Over 25mm Thru Paint



9: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint



10: Wheel nsr  
Scratched  
Over 50mm



11: Bumper Rear  
Scratched  
25 to 100mm Thru Paint



12: Qtr Panel osr  
Dented  
Over 30mm



13: Wheel osr  
Scratched  
Over 50mm



14: Door osr  
Scratched  
UpTo 25mm Thru Paint



15: Door osf  
 Scratched  
 Over 25mm Thru Paint



16: Sill os  
 Dented  
 Over 30mm



17: Wing osf  
 Scratched  
 Over 25mm Thru Paint



18: Wheel osf  
 Scratched  
 Over 50mm

**Interior**

**Carpet Condition**                      Average  
**Seat Condition**                        Average

**Upholstery Condition**              Average  
**Odour**                                      No

**Vehicle Inspection Report**

**Disclaimer**

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK