

# VEHICLE INSPECTION REPORT

**YC09YPL**

## BMW 1 Series 118d M Sport 3dr Step Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC

nama  
GRADE  
**4**

### Details

Reg. date	16/06/2009	Colour	GREY	MOT Due	15/09/2026
Year	2009	VIN	WBAUB32030VG00525	Gearbox	AUTOMATIC
Mileage	126,547 Miles Warranted	Body Style	Hatchback	Gears	6
Fuel Type	Diesel	Keys	2	Doors	3

£100 ADDITIONAL FEE. Heath shield rattle


### Tyres

NSF	BUDGET	6.0mm
NSR	DUNLOP	5.0mm
OSF	BUDGET	6.0mm
OSR	DUNLOP	5.0mm
Spare		

### Features


- Cruise control
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Front parking sensor
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Partial leather seat trim
- PAS
- Radio/CD
- Air conditioning
- Front head restraints
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Metallic Paint
- Drivers airbag
- Central locking

### Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Over 5mm



2: Bumper Front  
Poor Previous Repair  
Paint Flake



3: Wheel nsf  
Scratched  
Up To 50mm



4: Wing nsf  
Scratched  
Over 25mm Thru Paint



5: Door nsf  
Chipped  
1 To 5



6: Qtr Panel nsr  
Chipped  
1 To 5



7: Qtr Panel nsr  
Dented  
Over 30mm



8: Bumper Rear  
Scratched  
25 to 100mm Thru Paint



9: Qtr Panel osr  
Dented  
Between 10mm + 30mm



10: Qtr Panel osr  
Chipped  
1 To 5



11: Door osf  
Chipped  
Edge Chip



12: Roof  
Chipped  
Over 5mm



13: A Post os  
Chipped  
1 To 5



14: Wing osf  
Chipped  
1 To 5



15: Wheel of  
Scratched  
Up To 50mm



16: Seat Back Cover of  
Scuffed  
Over 25mm

### Interior

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK