



VEHICLE INSPECTION REPORT

LG60VNE

VOLKSWAGEN POLO 1.4 SEL 5dr

Inspection	Vehicle
	VAT Margin
	V5 Present

Details

Reg. date	03/09/2010	Body Style	Hatchback	MOT Due	03/09/2026
Year	2010	Service history	Yes	Gearbox	MANUAL
Mileage	72,702 Miles Warranted	Service documents	Service Book	Gears	5
Fuel Type	Petrol	Number of stamps	15	Doors	5
Colour	BLUE	Last service date	22/08/2025		
VIN	WVWZZZ6RZAU069709	Last service miles	71,360		

£90 ADDITIONAL FEE.
 last service 22/8/25 @ 71,360 miles (15 main dealer)
 cambelt and water pump replaced on 16/8/21 @ 60,791 miles

Tyres

NSF
NSR
OSF
OSR
Spare