



VEHICLE INSPECTION REPORT

YL72FLB

Vauxhall Corsa 1.2 Turbo Ultimate 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	10/02/2023	Body Style	Hatchback	Last service miles	16,031
Year	2023	Keys	2	MOT Due	06/01/2027
Mileage	27,149 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	6
Colour	BLACK	Number of stamps	2	Doors	5
VIN	VXKUPHNEKP4008361	Last service date	13/02/2025		

£90 ADDITIONAL FEE.

Last service 13/02/2025 at 16031 miles (2 main dealer services). Some panels required machine polish
 Service spanner displayed

Tyres


NSF	MICHELIN	5.0mm
NSR	PIRELLI	5.0mm
OSF	DAVANTI	5.0mm
OSR	PIRELLI	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Body coloured bumpers
- Folding rear seats
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- Park assist camera
- Service indicator
- Electric door mirrors
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Partial leather seat trim
- Front parking sensor
- PAS
- Steering wheel mounted controls
- Front fog lights
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Heated front seat
- Rear parking sensor
- Digital radio
- Air conditioning
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos




1: Bonnet
Scratched
Over 25mm Thru Paint



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Door nsf
Chipped
Edge Chip



4: Door osr
Chipped
1 To 5



5: Qtr Panel nsr
Dented
With Paint Damage



6: Bumper Rear
Scratched
Over 100mm Thru Paint



7: Qtr Panel osr
Dented
With Paint Damage



8: Door osr
Dented
With Paint Damage



9: Door osf
Chipped
1 To 5

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	Fault
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK