

# VEHICLE INSPECTION REPORT

**EF12XFE**

## Fiat 500 0.9 TwinAir Lounge 3dr

nama  
 GRADE  
**3**

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

### Details

Reg. date	27/06/2012	Body Style	Hatchback	Last service miles	21,421
Year	2012	Keys	1	MOT Due	19/11/2026
Mileage	71,190 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Electronic / Online	Gears	5
Colour	WHITE	Number of stamps	1	Doors	3
VIN	ZFA31200000858317	Last service date	17/07/2015		

last service 17/7/15 @ 21,421 miles (1 main dealer) confirmed by ST Leonards Motors LTD Exhaust blowing  
 Multiple panels will require machine polish

### Tyres

NSF	BUDGET	2.0mm
NSR	TRACMAX	5.0mm
OSF	BUDGET	3.0mm
OSR	TRACMAX	5.0mm
Spare		

### Features


- Rear wiper
- Fixed panoramic glass roof
- Rear headrests
- Passenger airbag
- Alloy wheels
- Radio/CD
- Air conditioning
- Solid Paint
- Central locking
- Body coloured bumpers
- Climate control
- ABS
- Remote central locking
- Electric door mirrors
- Front electric windows
- Drivers airbag
- Cloth seat trim

### Photos





## Condition Check



## Damage Photos



1: Wheel osf  
Scratched  
Over 50mm



2: Door osf  
Chipped  
Edge Chip



3: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint



4: Wheel osr  
Scratched  
Over 50mm



5: Bumper Rear  
Scratched  
Over 100mm Thru Paint



6: Door nsf  
Dented  
With Paint Damage



7: Wheel nsf  
Scratched  
Over 50mm



8: Wheel nsr  
Scratched  
Over 50mm



9: Bonnet  
Chipped  
1 To 5



10: Bumper Front  
Chipped  
Multiple Chips



11: Bumper Front  
Scratched  
25 to 100mm Thru Paint

### Interior

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK