



VEHICLE INSPECTION REPORT

KV12JHU

Volkswagen Tiguan 2.0 TDi Sport 170 5dr

nama
GRADE
2

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	18/06/2012	Body Style	Estate	Last service miles	105,606
Year	2012	Keys	2	MOT Due	24/10/2026
Mileage	109,225 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Service Book	Gears	6
Colour	GREY	Number of stamps	15		
VIN	WVGZZZ5NZCW067305	Last service date	25/10/2025		

Last Service - 02.10.2025 at 105606 miles (15 services)
 Cambelt Replaced 25.10.2024 @ 99360 Miles Multiple panels will require machine polish

Tyres

NSF	BUDGET	4.0mm
NSR	NEXEN	5.0mm
OSF	BUDGET	3.0mm
OSR	NEXEN	5.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Cruise control
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Navigation system
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Wheel osf
Corroded
Light



2: Wing osf
Chipped
1 To 5



3: Door osf
Chipped
1 To 5




4: Door osr
Chipped
1 To 5



5: Wheel osr
Corroded
Light



6: Boot Lid
Dented
Between 10mm + 30mm



7: Bumper Rear
Scratched
25 to 100mm Thru Paint



8: Wheel nsr
Corroded
Light



9: Door nsr
Chipped
1 To 5



10: Door nsf
Chipped
1 To 5



11: Door nsr
Dented
2 Or Less UpTo 10mm



12: Wheel nsf
Corroded
Light



13: Bumper Front
Scratched
25 to 100mm Thru Paint



14: Bonnet
Chipped
1 To 5



15: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK